

SOUŘADNICE - VÝTLAKY PŘISTOUPIM

výtlač V1

ČS1	-1050039.95	-710836.65
V1	-1050037.73	-710841.83
V2	-1050031.05	-710840.96
V3	-1050021.27	-710831.54
V4	-1050011.28	-710841.76
V5	-1050000.72	-710842.42
V6	-1049929.22	-710809.50
V7	-1049921.33	-710797.93
V8	-1049916.04	-710795.82
V9	-1049915.15	-710791.44
PŠ	-1049924.88	-710779.98

výtlač V2

ČS2	-1050635.87	-710911.64
V9	-1050604.56	-710910.88
V10	-1050531.25	-710916.39
V11	-1050531.25	-710918.93
V12	-1050335.27	-710901.01
V13	-1050329.57	-710897.20
Š7	-1050301.35	-710890.71

výtlač V3

ČS3	-1050355.71	-711072.77
V14	-1050312.42	-711069.53
V15	-1050308.59	-711070.28
Š20	-1050259.12	-711064.43

výtlač V4

ČS4	-1051060.40	-710844.22
V16	-1051046.15	-710848.23
V17	-1051041.91	-710861.80
V18	-1051022.48	-710897.32
V19	-1050987.31	-710936.29
V20	-1050976.70	-710938.02
V21	-1050966.34	-710928.32
V22	-1050958.86	-710925.85
V23	-1050948.15	-710960.03
V24	-1050947.06	-710961.35
V25	-1050943.45	-710972.87
V26	-1050942.49	-710977.86
V27	-1050934.42	-710980.50
Š44	-1050925.85	-710982.22